

**Office of the Executive Engineer
Building Division, Begusarai**

Letter No:-832.....

Date:-.....08/5/2023.....


TO WHOM IT MAY CONCERN

This is to certify that **Doon Public School, Ramzanpur, Begusarai (Bihar), PIN-851129** is functioning in the framed structure building (G+5). It has sufficient well-ventilated classrooms for students. There is hygienic environment in the school campus for the children. The school building has three stairs with S.S. railing, which is sufficient for emergency exit. There is separate toilet and drinking water facility for girls and boys at each floor, which is sufficient in number. There is one lift well in which lift installation is in progress.

The school building has its own playground and park for children.

The aforesaid school building looks safe for conducting classes and is situated in the safe zone of this area.

This letter is valid up to one year from its issue date.



Executive Engineer
Building Division, Begusarai
Begusarai


**PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE**

Memo No. 572Dated 03/05/23

It is certified that an inspection team headed by Sri Prabhas Gautam, Assistant Engineer, P. H. Sub. Division, Begusarai from Doon Public School, Ramzanpur, Begusarai, Bihar on 03.05.2023 and found that the Doon Public School, Ramzanpur, Begusarai, Bihar has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygenic sanitation condition in the school building & the campus as per norms prescribed by the Central/State Govt.

The above is valid for a period of 1 year.



**Executive Engineer
P.H.Division, Begusarai**